CH 1

CH 2

CH 3

CH 4

BIAS OUTPUT TRANSFORM

TYPE NO(A)TO
( )AT THE END

PB-76D MOTHER PCB ASS'Y
PB76DOA CIRCUIT DIAGRAM