





TRANSPORT CONTROL PCB

LOCATOR CONNECTOR PIN NO.



• REMOVE AND INSULATE THE EXISTING WIRES TO THESE PINS
ADD NEW WIRES TO PINS 6, 7, 8, 9 AS SHOWN